
The background of the slide is a faded photograph of firefighters inside a fire truck cab. One firefighter in the foreground is wearing a helmet with the number '19' and is looking towards the camera. Another firefighter is visible in the background. The overall scene is brightly lit, likely from the truck's interior lights.

Photo Album for E. Greenwich, RI

Job 21614

December 20, 2008

This week the cab finished in paint and began on the cab line where cab related content is added. The chassis was assembled and painted. Pump and body fabrication finished and were painted. By the next report the cab and pump should be merged with the chassis. The body should have harnessing and trim added and may also be merged with the chassis. Due to the plant holiday shutdown, your next report will be sent by January 10th.



DSC00855



DSC00856



DSC00857



DSC00858



DSC00859



DSC00169



DSC00170



DSC00171



DSC00172



DSC00173




DSC06018



DSC06019



DSC06020



DSC06021



DSC06022



DSC06023



DSC06024



DSC06025



DSC06348



DSC06349



DSC06350



DSC06351



DSC06352